



AGAP-S

C-FSJB

December 2008/January 2009

# PILOT FLIGHT LOG

Flight Number	26
Date (ZULU)	Jan. 6/09
Pilot/Co-Pilot	Larson / MacNeil
Operator(s)	Felix Goldman
Information	

**Max bank angle: < 15° during entire flight.**  
**No radio communications during survey lines. No electric heat during survey lines.**  
**Wingtip fuel pumps and wing tip strobe lights off during survey lines.**

Event	Zulu Time	Comments
HF radio	0824	
Tip tank on	0825	returned to AGAPS - GPS failure on survey equipment
tips on	1025	
HF call	1025	
tips off	1120	
HF call	1125	
HF call	1225	
HF	1325	